



Stream Segment 13 Components

Remove failing concrete channel liner, construct channel stability improvements from 0+00 to 5+00 and reestablish riparian vegetation
See Figure SG3-CD3

Establish floodplain from 0+00 to 21+00

Establish right-of-way from 0+00 to 21+00 for management access

